

DEPARTMENT OF TRANSPORTATION

DIVISION OF ENGINEERING SERVICES

Office of Structural Materials

Quality Assurance and Source Inspection



Bay Area Branch

690 Walnut Ave.St. 150

Vallejo, CA 94592-1133

(707) 649-5453

(707) 649-5493

Contract #: 04-0120F4Cty: SF/ALA Rte: 80 PM: 13.2/13.9File #: 69.28**WELDING INSPECTION REPORT****Resident Engineer:**Pursell, Gary**Address:** 333 Burma Road**City:** Oakland, CA 94607**Report No:** WIR-005963**Date Inspected:** 20-Mar-2009**Project Name:** SAS Superstructure**OSM Arrival Time:** 645**Prime Contractor:** American Bridge/Fluor Enterprises, a JV**OSM Departure Time:** 1845**Contractor:** Zhenhua Port Machinery Company, Ltd (ZPMC), Changxing Island **Location:** Shanghai ,China**CWI Name:** Li Yan Hua**CWI Present:** Yes No**Inspected CWI report:** Yes No N/A**Rod Oven in Use:** Yes No N/A**Electrode to specification:** Yes No N/A**Weld Procedures Followed:** Yes No N/A**Qualified Welders:** Yes No N/A**Verified Joint Fit-up:** Yes No N/A**Approved Drawings:** Yes No N/A**Approved WPS:** Yes No N/A**Delayed / Cancelled:** Yes No N/A**Bridge No:** 34-0006**Component:** OBG Assembly**Summary of Items Observed:**

On this date CALTRANS OSM Quality Assurance (QA) Inspector was present during the times noted above for observations relative to the work being performed.

Segment Repair Yard (South of the paint shop)

Segment 5AW

This QA Inspector performed Magnetic Particle testing (MT) of approximately 15% of the area previously tested and accepted by ZPMC Quality control personnel. This QA inspector generated a (MT) report for this date. The members are identified as the deck panel diaphragm welds. The Weld Designations are as follows:

DP108-001-024, 025, 027, 030, 029, 060, 061, 063, 066 and 065.

DP081-013, 014, 016, 018, 019, 041, 042, 044, 047 and 046.

DP135, 026, 027, 029, 031, 032, 071, 072, 077, 074, and 076.

DP108-024, 025, 027, 030, 029, 060, 061, 063, 066 and 065.

DP162-026, 027, 029, 032, 031, 071, 072, 074, 077 and 076.

DP189-026, 027, 029, 032, 031, 071, 072, 074, 077 and 076.

DP216-035, 036, 038, 041, 040, 071, 072, 074, 077 and 076.

DP243-026, 027, 029, 032, 031, 079, 080, 082, 085, and 084.

DP270-022, 023, 025, 028, 027, 049, 050, 052, 055 and 057.

This QA Inspector performed a preliminary random visual inspection of the internal structure of this segment. Areas that were marked to be ground and welded were repaired at the time of inspection.

WELDING INSPECTION REPORT

(Continued Page 2 of 2)

Unless otherwise noted, all work observed on this date appeared to generally comply with applicable contract documents.

Summary of Conversations:

No Relevant conversations

Comments

This report is for the purpose of determining conformance with the contract documents and is not for the purpose of making repair or fit for purpose recommendations. Should you require recommendations concerning repairs or remedial efforts please contact Eric Tsang, (15000422372), who represents the Office of Structural Materials for your project.

Inspected By:	Patterson,Rodney	Quality Assurance Inspector
Reviewed By:	Carreon,Albert	QA Reviewer
